

Report Date: 20-Oct-2009

Selection Range : 01-Jan-2000

To 20-Oct-2009

**OPEN FAULT REPORT**

FOR: WTQHC0

MODEL: UH-60L

SERIAL NUMBER: 9126321

HOURS: 3194.8

NEXT PHASE: 3539

LAST MISSION: 12-Jan-2009

Current Status A: **X**

Current Status E: **/**

Current Status O:

Current Status W:

DISCOVERY						CORRECTION					
SYSTEM	CODE	DATE / TIME	NO	STATUS	PID	HOURS	DATE / TIME	HOURS	ROUNDS	ACTCD	WUC
	A	10/23/2008 1:07 pm	1,006	/	MG816772	3,179.3					
<b>FAULT WRITE-UP:</b> SEARCH LIGHT ONLY OPERATES WITH DIMMING CONTROL UNIT SWITCH ON BYPASS. SEARCH LIGHT DIMMING INOP. PART ON ORDER.(TRANSCRIBED FROM ULLS-A(E) PHASE: WTQHC08197001 ON Nov 13 2008 3:58PM)						<b>ACTION TAKEN:</b>					
	WHEN DISC	HOW REC	MAL EFF	WUC	MAINT TYPE	DEFERRED DAYS	TIPID	MMH	PID	MMH	TYPE
	B	G	2	09	O						
<b>DELAY</b> PART ON ORDER											
	A	12/16/2008 2:40 pm	12	/	CP134947	3,188.8					
<b>FAULT WRITE-UP:</b> R/H MLG STRUT LOWER PISTON SEEPING HYD FLUID						<b>ACTION TAKEN:</b>					
	WHEN DISC	HOW REC	MAL EFF	WUC	MAINT TYPE	DEFERRED DAYS	TIPID	MMH	PID	MMH	TYPE
	O	O	1	03	O						
<b>DELAY</b>											
	A	12/16/2008 2:48 pm	15	/	CP134947	3,188.8					
<b>FAULT WRITE-UP:</b> #2 GENERATOR WIRE HARNESS OUTER INSULATION WORN AND TEMP REPAIRED AT CLAMP						<b>ACTION TAKEN:</b>					
	WHEN DISC	HOW REC	MAL EFF	WUC	MAINT TYPE	DEFERRED DAYS	TIPID	MMH	PID	MMH	TYPE
	O	O	1	09	O						
<b>DELAY</b>											
	A	12/16/2008 5:13 pm	16	/	CP134947	3,188.8					
<b>FAULT WRITE-UP:</b> ACCUMULATOR "TAPE" GAUGE HAS HYD FLUID IN VIEW						<b>ACTION TAKEN:</b>					
	WHEN DISC	HOW REC	MAL EFF	WUC	MAINT TYPE	DEFERRED DAYS	TIPID	MMH	PID	MMH	TYPE
	O	O	1	07	O						
<b>DELAY</b>											

Report Date: 20-Oct-2009

Selection Range : 01-Jan-2000 To 20-Oct-2009

**OPEN FAULT REPORT**

FOR: WTQHC0

MODEL: UH-60L

SERIAL NUMBER: 9126321

HOURS: 3194.8

NEXT PHASE: 3539

LAST MISSION: 12-Jan-2009

Current Status A: **X**

Current Status E: **/**

Current Status O:

Current Status W:

DISCOVERY						CORRECTION					
SYSTEM	CODE	DATE / TIME	NO	STATUS	PID	HOURS	DATE / TIME	HOURS	ROUNDS	ACTCD	WUC
	E	12/17/2008 2:23 pm	1	/	JR337029	3,188.8					
<b>FAULT WRITE-UP:</b> H/F ANTENNA GASKETS AND CONNECTOR STREACH SEAL TAPE NOT INSTALLED. PARTS ON ORDER.						<b>ACTION TAKEN:</b>					
<b>WHEN</b>	<b>HOW</b>	<b>MAL</b>	<b>WUC</b>	<b>MAINT</b>	<b>DEFERRED</b>		<b>TIPID</b>	<b>MMH</b>	<b>PID</b>	<b>MMH</b>	<b>TYPE</b>
<b>DISC</b>	<b>REC</b>	<b>EFF</b>		<b>TYPE</b>	<b>DAYS</b>						
K	G	2	19	O							
DELAY											
DISCOVERY						CORRECTION					
SYSTEM	CODE	DATE / TIME	NO	STATUS	PID	HOURS	DATE / TIME	HOURS	ROUNDS	ACTCD	WUC
	A	12/31/2008 8:21 am	1	/	CP134947	3,189.3					
<b>FAULT WRITE-UP:</b> L/H T/R QUADRANT SWITCH HAS TEMPORARY REPAIRED ON BACKSHELL						<b>ACTION TAKEN:</b>					
<b>WHEN</b>	<b>HOW</b>	<b>MAL</b>	<b>WUC</b>	<b>MAINT</b>	<b>DEFERRED</b>		<b>TIPID</b>	<b>MMH</b>	<b>PID</b>	<b>MMH</b>	<b>TYPE</b>
<b>DISC</b>	<b>REC</b>	<b>EFF</b>		<b>TYPE</b>	<b>DAYS</b>						
O	O	1	09	O							
DELAY											